



Contractor Yard  
City of Buena Park  
Chip Seal with PG70-22TR

*Applied in 2007*

Pictures taken in 2010









repetitive  
movement of  
heavy equipment  
with turning  
radius stresses





Heavy and  
slow moving  
equipment  
over the chip  
seal

Chipped section  
Good resistance  
for cracks  
propagation

chipped

This section  
wasn't chipped  
and cracks had  
disappeared in  
the section that  
was chipped  
above the dotted  
line

Not chipped